

Cnsi Drill Press SOP

Revised Aug 2020. Compiled with help from the UCSB ME Design Lab SOP written by Dr. Trevor Marks.

Location

The Wen 15" Floor Standing Drill Press is located in 2448 Elings Hall

Safety Concerns

Eye injuries can result from flying chips or broken bits. Cuts can occur from contacting sharp tools or exposed chips and burrs. Burns can result from hot cutting tools or parts. Metal splinters can result from exposed burrs or chips. Serious injury can result from pinching or entanglement in moving parts. Poor housekeeping creates tripping and cutting hazards for other users. Do not leave machine running unattended.



From:

<https://bpm-wiki.cnsi.ucsb.edu/> - NSF BioPACIFIC MIP Wiki

Permanent link:

https://bpm-wiki.cnsi.ucsb.edu/doku.php?id=drill_press_sop&rev=1597428932

Last update: **2020/08/14 18:15**

